

Work Order ID 139281

Thursday, March 10, 2016 11:37:30 AM

139281

Page 1

Item ID: D350-588-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Aft Door Assembly

Stop

NS2

Start Date: 11/19/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 12/18/2015 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: *[Signature]*

Date: 16.3.10

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2445/D350-588	Rev D/D								
DSI9690	A								

100

100

DC

Doc.Control -USB or Paperwork

Document Control

DOCUMENT CONTROL

0.00

Memo

0.00

Photocopy bluefile and create labels per PPP D350-588-041 CHG003

DAS
6
9-89

DAS
28
9-89

MAR 11 2016
MAR 14 2016

110

110

Purchasing

Purchasing

PURCHASING

Memo

0.00

Issue P/O: *30535*
Description: D2445 Baggage Door
Supplier: Delastek
Ship to Delastek (1) D0588-041 label
Certification of Conformity and process sheet from Delastek is required.

DAS
13
9-89

MAR 10 2016

REPRINT

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : ☐			

Work Order ID 139281

Thursday, March 10, 2016 11:37:30 AM

139281

Page 2

Item ID: D350-588-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Aft Door Assembly

Start Date: 11/19/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 12/18/2015 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	Receive & Inspect for Damage & Mat'l Certs	0.00							
120									
Packaging	Memo	0.00							
Packaging	Ensure Certificate of Conformity & Process Sheet are attached								
130	QC6- Inspect dimensions to drawing	0.00							
130									
QC	Memo	0.00							
Quality Control	Inspect as per Dwg D2445. Audit process sheet.								
140	Small Fab	0.00							
140									
Small Fab	Memo	0.02							
Small Fab	Assemble all of the above parts as per Dwg D350-588								

1x SP 16-02-17.
1x SP 16-03-8.

② 16-03-10

DAS
9
9-89

x1
16/03/10.

DAS
07
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : ☐			

Work Order ID 139281

Thursday, March 10, 2016 11:37:30 AM

139281

Page 3

Item ID: D350-588-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Aft Door Assembly

Stop

NS2

Start Date: 11/19/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 12/18/2015 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

150

QC5- Inspect part completeness to step on W/O

0.00

150

QC

Memo

0.00

Quality Control

① 16-03-10 DAS
9-89

155

Pick Kit

0.00

155

Packaging

Memo

0.00

Packaging

DAS
27
9-89
MAR 14 2016

160

QC4- 100% Inspect kits for completeness

0.00

160

QC

Memo

0.00

Quality Control

DAS
28
9-89

MAR 14 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐				
Date :	Step #:	QTY Effective :			MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
		OTHER : ☐				

Work Order ID 139281

Thursday, March 10, 2016 11:37:30 AM

139281

Page 4

Item ID: D350-588-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Aft Door Assembly

Stop ***NS2***Start Date: 11/19/2015 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 12/18/2015 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
170	Identify as per dwg & Stock Location:	0.00				DAS 28 9-89	DAS 27 9-89		
170									
Packaging	Memo	0.00							
Packaging	Location :FG021								
180	QC21- Final Inspection - Work Order Release	0.00							
180									
QC	Memo	0.00							
Quality Control									

16/1/14 *[Signature]*
16-03-14

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : ☐							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, March 10, 2016 1:01:19 PM

Page 1

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP P 04.02.04ReformatKJ/DS IPP Rev:Q as
per DSI9414 DD verified by:EC IPP Rev:R add pick kit DD
10.03.29 verified by:EC IPP REV:S 14.04.28 AS PER
DSI9690 DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2445P		Purchased	No			110	Each	0.0000	1	1			
										**	1X SP 16-02-17		
D2445P													
Aft Door Assembly													
AN526C832R9		Purchased	No			140	Each	541.0000	8	8			
										**	DAS 07 9-89		
AN526C832R9													
Screw													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					16/02/25
				ST327		341							
				M132823		66							
				M133932		150							
				M134063		125							
				ST328		200							
				M134376		200							
D2143		Manufactured	No			140	Each	12.0000	1	1			
										**	DAS 07 9-89		
D2143													
Hinge Bracket													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					16/02/25
				ST003		12							
				121806		12							
D2144		Manufactured	No			140	Each	2.0000	1	1			
										**	DAS 07 9-89		
D2144													
Hinge Doubler													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					16/02/25
				ST002		2							
				114332		2							

DAS
07
9-89

DAS
07
9-89

DAS
07
9-89

16/02/25

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	☐	Manufacturing Process ☐							
Misidentified ☐	☐	Past Due ☐	OTHER : _____						

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 2

Work Order ID: 139281

Parent Item: D350-588-041

Parent Item Name: Aft Door Assembly

139281

D350-588-041

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

D2463

Manufactured No

140 f

527.1991

7.25

7.25

D2463

1/2" Seal (\$Per Foot)

**DAS
07
9-89**

16/02/25

Location

Loc Qty

Loc Code

ST409

500

140013

500

ST638

27.19906833

125469

27.1990683

(D2463-0870) cut (1) at 87.00"
**** per kit****

D2585

Manufactured No

140 Each

7.0000

2

2

D2585

Latch Clamp

**DAS
07
9-89**

16/02/25

Location

Loc Qty

Loc Code

ST008

7

139075

7

D2586

Manufactured No

140 Each

81.0000

2

D2586

Door Latch

**DAS
07
9-89**

16/02/25

Location

Loc Qty

Loc Code

FG

12

119746

1

138048

2

139228

9

ST481

19

139228

19

ST488a

50

140535

25

141454

25

Thursday, March 10, 2016 1:01:20 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	☐	Manufacturing Process ☐							
Misidentified ☐	☐	Past Due ☐	OTHER : ☐						

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 3

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

D2621

Manufactured No

140

Each

10.0000

2

2

D2621

Latch Plate

DAS
07
9-89

Location

Loc Qty

Loc Code

FG

2

88616

2

ST009

8

127749

8

D2857-1

Manufactured No

140

Each

20.0000

1

1

D2857-1

Hinge Bracket

DAS
07
9-89

Location

Loc Qty

Loc Code

FG

5

121829

2

82261

2

91914

1

ST012

3

121829

1

133964

2

ST012a

12

141046

12

D2857-2

Manufactured No

140

Each

24.0000

1

1

D2857-2

Hinge Bracket

DAS
07
9-89

Location

Loc Qty

Loc Code

FG

5

130848

2

78904

3

ST012

1

133903

1

ST012a

18

140972

18

Thursday, March 10, 2016 1:01:20 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong				
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions				
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance				
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect				
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing				
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved				
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing				
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish				
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread				
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence				
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____							
Misidentified ☐	☐ Past Due								

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 4

Work Order ID: 139281

Parent Item: D350-588-041

Parent Item Name: Aft Door Assembly

139281

D350-588-041

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

MS21042L08

Purchased

No

140

Each

1,675.000

8

8

MS21042L 08

Nut

DAS
07
9-89

Location

Loc Qty

Loc Code

CA

101

m129682

101

GA

161

m133134

3

m134063

158

OVER007

500

m134063

500

ST303

513

m133922

513

ST308

400

m134376

400

MS21042L3

Purchased

No

140

Each

2,922.000

2

2

MS21042L 3

Nut

DAS
07
9-89

Location

Loc Qty

Loc Code

FP001

163

m133790

163

GA

68

m133790

68

OVER007

2000

m134360

2000

ST304

691

m134039

691

Thursday, March 10, 2016 1:01:20 PM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval																																																									
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 5

Work Order ID: 139281

Parent Item: D350-588-041

Parent Item Name: Aft Door Assembly

139281

D350-588-041

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

MS27039-1-15

Purchased

No

140

Each

470.0000

2

2

MS27039-1-15

Screw

DAS
07
9-89

Location

Loc Qty

Loc Code

GA

21

m127916

21

ST280

449

m132640

449

NAS1149D0363J

Purchased

No

140

Each

1,916.000

2

2

NAS1149D0363.J

Washer

DAS
07
9-89

Location

Loc Qty

Loc Code

GA

64

m133932

m130799

64

ST263

1852

m134055

852

m134370

1000

NAS1149DN832J

Purchased

No

140

Each

2,171.000

8

8

NAS1149DN832.J

Washer

DAS
07
9-89

Location

Loc Qty

Loc Code

CA

84

M129499

84

ST260a

1500

M134180

1500

ST263

587

M131697

587

Thursday, March 10, 2016 1:01:20 PM

Shop Packet Print

Page 5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				mRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 6

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

AN526C1032R7

Purchased

No

155

Each

188.0000

2

2

AN526C1032R7

Screw

**

DAS
6

9-89

9-89

Location

Loc Qty

Loc Code

ST327

188

M128403

188

AN526C832R8

Purchased

No

155

Each

305.0000

8

8

AN526C832R8

Screw

**

DAS
6

9-89

9-89

Location

Loc Qty

Loc Code

ST327

305

m129706

94

m129764

11

m133932

100

m134376

100

D2150

Manufactured

No

155

Each

24.0000

2

2

D2150

Packer Doubler, Hinge

**

DAS
6

9-89

9-89

Location

Loc Qty

Loc Code

ST003

24

121844

24

D2151

Manufactured

No

155

Each

15.0000

2

2

D2151

Packer Doubler

**

DAS
6

9-89

9-89

Location

Loc Qty

Loc Code

ST003

15

121825

15

MAR 11 2016

Thursday, March 10, 2016 1:01:20 PM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 7

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

D2153

Manufactured No

155 Each

65.0000

1 1

D2153

Door Prop

Location

Loc Qty

Loc Code

ST362

29

131670

4

140759

25

ST370a

36

141726

36

D2154

Manufactured No

155 Each

31.0000

1 1

D2154

Bracket, Stud

Location

Loc Qty

Loc Code

ST003

31

118894

31

D2237

Manufactured No

155 Each

40.0000

2 2

D2237

Striker Plate

Location

Loc Qty

Loc Code

ST004

40

136090

10

140960

30

D2461

Manufactured No

155 f

295.0074

7.25 7.25

D2461

Neoprene 'D' Seal (\$Per Foot)

Location

Loc Qty

Loc Code

ST407

295.00737

128447

295.00737

(D2461-0870) cut (1) at 87.00"
**** per kit****

DAS
28
9-89

MAR 11 2016

MAR 11 2016

Thursday, March 10, 2016 1:01:20 PM

Shop Packet Print

Page 7

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY					
Environment ☐		No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐		
Design ☐		Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐		Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐		Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐		Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐		Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐		Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐		Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐		Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐		Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐		Manufacturing Process ☐	OTHER : ☐					
Misidentified ☐		Past Due ☐						

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 8

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

D2589

Manufactured Yes

155

Each

7.0000

1

1

D2589

Keys, Key Chain

DAS
28
9-89

**

DAS
6
9-89
DAS
27
9-89

Location

Loc Qty

Loc Code

ST008

7

132942

7

D2690-17

Manufactured No

155

Each

24.0000

1

1

D2690-17

Cable

**

Location

Loc Qty

Loc Code

ST012a

24

112206

6

120107

3

121750

6

140042

9

DAS
6
9-89
DAS
27
9-89

D2858-1

Manufactured No

155

Each

40.0000

1

1

D2858-1

Hinge Bracket

**

Location

Loc Qty

Loc Code

FG

2

77019

2

ST012

14

121400

2

133091

12

ST012a

24

140966

24

DAS
28
9-89

MAR 11 2016

DAS
6
9-89
DAS
27
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		☐ OTHER : _____							

Picklist Print

Thursday, March 10, 2016 1:01:20 PM

Page 9

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

D2858-2

Manufactured No

155

Each

30.0000

1

1

D2858-2

Hinge Bracket

DAS
28
9-89

Location

Loc Qty

Loc Code

FG

2

77020

2

ST012

28

121563

4

141043

24

D5080-041

Manufactured No

155

Each

43.0000

2

2

D5080-041

Striker Plate Assembly

DAS
28
9-89

Location

Loc Qty

Loc Code

ST148

43

121798

2

126722

17

128722

24

FG-778150-550-ROL

Purchased

No

155

sf

576.1463

1

1.333333

***FG-778150-550-ROL ***

7781 9oz Glass 50x125yd

DAS
28
9-89

Location

Loc Qty

Loc Code

CA2

576.1463415

M127701

576.146342

CUT ONE SQUARE FEET PER KIT

MAR 11 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Thursday, March 10, 2016 1:01:21 PM

Page 10

Work Order ID: 139281

Parent Item: D350-588-041

Parent Item Name: Aft Door Assembly

139281

D350-588-041

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

MS20426AD3-4

Purchased

No

155

Each

6,351.000

12

12

MS20426AD3-4

RIVET

DAS
28
9-89

Location

Loc Qty

Loc Code

CCK004

4885

m134294

4885

GA

1008

m131697

1008

ST312

458

m131697

458

12

MS20470AD4-5

Purchased

No

155

Each

1,320.000

18

18

MS20470AD4-5

RIVET, UNIVERSAL HEAD

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

914

m133860

914

ST310

406

m133860

406

18

DAS
28
9-89

MAR 11 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐				
Date :	Step #:	QTY Effective :			MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
		OTHER : ☐				

Picklist Print

Thursday, March 10, 2016 1:01:21 PM

Page 11

Work Order ID: 139281

139281

Parent Item: D350-588-041

D350-588-041

Parent Item Name: Aft Door Assembly

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

MS21042L08

Purchased

No

155

Each

1,675.000

10

10

MS21042L 08

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

CA

101

m129682

101

GA

161

m133134

3

m134063

158

OVER007

500

m134063

500

ST303

513

m133922

513

ST308

400

m134376

400

70

DAS
6
27
9-89

MS21042L3

Purchased

No

155

Each

2,922.000

4

4

MS21042L 3

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

FP001

163

m133790

163

GA

68

m133790

68

OVER007

2000

m134360

2000

ST304

691

m134039

691

4

DAS
6
27
9-89

MAR 11 2016

Thursday, March 10, 2016 1:01:21 PM

Shop Packet Print

Page 11

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐ Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐				FAULT CATEGORY Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐							

Picklist Print

Thursday, March 10, 2016 1:01:21 PM

Page 12

Work Order ID: 139281

Parent Item: D350-588-041

Parent Item Name: Aft Door Assembly

139281

D350-588-041

Start Date: 11/19/2015

Required Date: 12/18/2015

Start Qty: 1.00

Required Qty: 1.00

MS27039-08-11

Purchased

No

155

Each

372.0000

2

2

MS27039-08-11

SCREW

**

DAS

6

9-89

DAS

27

9-89

Location

Loc Qty

Loc Code

ST278

372

m133769

372

2

NAS1149D0363J

Purchased

No

155

Each

1,916.000

2

2

NAS1149D0363J

Washer

**

DAS

6

9-89

DAS

27

9-89

Location

Loc Qty

Loc Code

GA

64

m130799

64

ST263

1852

m134055

852

m134370

1000

2

NAS1149DN832J

Purchased

No

155

Each

2,171.000

16

16

NAS1149DN832J

Washer

**

DAS

6

9-89

DAS

27

9-89

Location

Loc Qty

Loc Code

CA

84

M129499

84

ST260a

1500

M134180

1500

ST263

587

M131697

587

16

MAR 11 2016

Thursday, March 10, 2016 1:01:21 PM

Shop Packet Print

Page 12

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date: _____		Step #: _____		QTY Effective : _____				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D350-588 REV. D AND
INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D350-588 REV. 0
REF TCCA STC SH92-41
FAA STC SH1012NE

1.0 PURPOSE:

The purpose of this Dart Service Instruction is to provide customers with directions to install a modified striker plate that will provide more clearance around environmental/conductive seals that protrude inboard of the door frame structure on AS355 N/NP models.

2.0 PROCEDURE:

- 1) Install D350-588-011/-041 per Section 3.1/3.2 of D350-588 as applicable, except do not install D2237 striker plates per item 10 of Section 3.1.
- 2) Remove the aft environmental/conductive seal to gain access to the door structure.
- 3) Using a fine point marker, mark location of both striker plates based on door latch location.
- 4) If D2237 Striker Plates are currently installed, remove both striker plates by drilling out rivets.
- 5) Align D5080-041 striker plate assembly in the previously marked location and transfer drill the $\varnothing 0.1285$ " (#30) holes into the aft bulkhead.
- 6) Drill out both rivets on the aircraft skin adjacent to the striker plate assemblies.
- 7) Align D5080-041 striker plate assembly in the previously marked location and transfer drill the $\varnothing 0.1285$ " (#30) holes from the aircraft skin to the striker plate assembly.
- 8) Deburr holes and remove all sharp edges.
- 9) Touch up all holes in aluminum with chemical conversion coating in accordance with MIL-DTL-5541.
- 10) Apply 0.125" thick layer of PR-1775B ProSeal to the face of D5080-041 per Figure 1.
- 11) Install D5080-041 striker plate assemblies to the aft bulkhead using CR3213-4 rivets of a suitable length, and to the skin of the aircraft using PR-1775B coated CR3213-4 rivets of a suitable length.
- 12) Reinstall environmental/conductive seal using manufacturers recommended procedure.
- 13) Install gas strut or cable assembly per D350-588 Figure 5.
- 14) Adjust both latch mechanisms to ensure adequate compression of door seal and that door skin is flush.
- 15) Check door for proper operation by opening and closing the door, and ensure latches fully lock.




Figure 1 Striker Plate

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 14.03.24
CERT. NO.: SH92-41
ISSUE NO.: 8

A	NEW ISSUE		ML	14.03.24
REV.	DESCRIPTION		BY	DATE
DESIGN	ML	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	REV. A SHEET 1 OF 2	
DRAWN	ML			
CHECKED				
MFG. APPR.				
APPROVED				
DE APPR.		TITLE	SCALE	
		STRIKER PLATE MOD	NTS	
DATE	14.03.24		COPYRIGHT © 2014 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT	

3.0 PARTS LIST:

The part lists of D350-588 Rev. D and ICA-D350-588 Rev. 0 are amended as follows.

IS:

588 -041	588 -011	PART NUMBER	DESCRIPTION
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MOD
2	2	D5080-041	STRIKER PLATE ASSY (AS355 N/NP MODELS ONLY)
2	2	D2237	STRIKER PLATE

WAS:

588 -041	588 -011	PART NUMBER	DESCRIPTION
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MOD
2	2	D2237	STRIKER PLATE

Customers who need to upgrade a D350-588-011/-041 kit that has been previously purchased from Dart can procure the DSI 9690-011 Kit from Dart.

QTY -011	PART NUMBER	DESCRIPTION
X	DSI 9690-011	STRIKER PLATE MODIFICATION KIT
2	D5080-041	STRIKER PLATE ASSEMBLY

4.0 WEIGHT AND BALANCE:

This DSI has a negligible effect on Weight and Balance of the aircraft.

5.0 MAINTENANCE:

Maintain the D5080-041 Striker Plates in accordance with the procedures for the D2237 Striker Plates as outlined in ICA-D350-588.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 14.03.24
CERT. NO.: SH82-41
ISSUE NO.: 8

DESIGN	ML	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	ML		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9690	SHEET 2 OF 2
APPROVED		TITLE	SCALE
DE APPR.		STRIKER PLATE MOD	NTS
DATE	14.03.24	COPYRIGHT © 2014 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

52.3 WEIGHT AND BALANCE

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
D350-588-011	1.0 lb	-21.0 in	-21.0 in-lb	+170.0 in	+170.0 in-lb
Aft Door Fwd Hinge Modification Kit	0.45 Kg	-0.53 m	-0.24 m-Kg	+4.32 m	+1.96 m-Kg
D350-588-041*	2.0 lb	-21.0 in	-42.0 in-lb	+170.0 in	+340.0 in-lb
Aft Door Assembly	0.91 Kg	-0.53 m	-0.48 m-Kg	+4.32 m	+3.93 m-Kg

* D350-588-041 Aft Door Assembly weight in excess of standard Eurocopter Door.

52.4 PARTS LISTS

588 -041	588 -011	Part Number	Description
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MODIFICATION KIT
1	1	D2143	HINGE DOUBLER
1	1	D2144	HINGE DOUBLER
2	2	D2150	HINGE PACKER
2	2	D2151	HINGE DOUBLER
1	1	D2153-3315-10	GAS SPRING ASSY.
1	1	D2154	STUD BRACKET
2	2	D2237	STRIKER PLATE
1		D2445	DOOR
1	1	D2461-0870	NEOPRENE D SEAL
1	1	D2463-0870	1/2" FOAM SEAL
	2	D2583	LATCH BRACKET
2	2	D2585	LATCH CLAMP
2	2	D2586	LATCH
	1	D2587	PLUG
1	1	D2589	KEYS, KEY CHAIN
2		D2621	LATCH PLATE
1	1	D2690-17	CABLE, DOOR STOP
1	1	D2857-1	LOWER HINGE BRACKET
1	1	D2857-2	UPPER HINGE BRACKET
1	1	D2858-1	LOWER HINGE BRACKET
1	1	D2858-2	UPPER HINGE BRACKET
8	8	AN526C832R8	SCREW (or AN526-832R8)
8	8	AN526C832R9	SCREW (or AN526-832R9)
2	2	AN526C1032R7	SCREW (or AN526-1032R7)
24	24	AN960JD8	WASHER
4	4	AN960JD10	WASHER
12	12	MS20426AD3-4	RIVET
18	18	MS20470AD4-5	RIVET
18	18	MS21042L08	NUT (or MS21042-08)
4	4	MS21042L3	NUT (or MS21042-3)
2	2	MS27039-1-15	SCREW
2	2	MS27039-0811	SCREW
1	1	N/A	1 SQUARE ft. OF 9 oz. GLASS CLOTH (S-CLASS)

• COPYRIGHT © 2002 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Work Order ID 139281

Thursday, March 10, 2016 11:37:30 AM

139281

Page 1

Item ID: D350-588-041

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Aft Door Assembly

Start Date: 11/19/2015 Start Qty: 1.00

1

Cust Item ID:

Required Date: 12/18/2015 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: 

Date: 6.3.10

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2445/D350-588	Rev D/D								
DSI9690	A								

100 Document Control
DOCUMENT CONTROL

0.00

100
DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile and create labels per PPP D350-588-041 CHG003

ML5 MAR 1 1 2016

110 PURCHASING

0.00

110
Purchasing

Memo


0.00

Purchasing

Issue P/O: 31001
Description: D2445 Baggage Door
Supplier: Delastek
Ship to Delastek (1) D0588-041 label
Certification of Conformity and process sheet from Delastek is required.

DAS
13
2-10

MAR 1 0 2016



RECEIVED FEB 06 2016

FDC Composites inc.
45, Chemin de L'Aéroport
Local 26
Saint-Jean-sur-Richelieu (QC)
J3B 7B5

Tél.: 450 357-1344

Facture

23/12/2015

FDC2344

Commande : 30535
Référence : PO #30535/1-2
Termes : Net 30 jours/days

Client : Dart

DART AEROSPACE
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7

Expédier à :
DART AEROSPACE LTD
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7 Tél.: 1 613 632-9577

No item	Description	Comm.	Fact.	Qté B/O	Prix	Total	Tx
D2445P	Aft Door Assembly B139280 PO item: 30535/1 Lot: 2015-12-01	1	1	0	67000	67000	A
D2445P	Aft Door Assembly B139281 PO item: 30535/2 Lot: 2016-01-07	1	1	0	67000	67000	A

CANADIAN CURRENCY

ENTERED FEB 10 2016

MAR 01 2016

19313

Sous-total :		1 34000
4) Inscrit : 83343 3220 RT0001	TVH-Ont. :	17420
Total :		1 514.20

FDC Composites inc.
45, Chemin de L'Aéroport
Local 26
Saint-Jean-sur-Richelieu (QC)
J3B 7B5
Tél. : 450 357-1344

Bon de livraison

23/12/2015

Commande : 2344
Référence : PO #30535/1-2

Client : Dart

DART AEROSPACE
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7

Expédier à

DART AEROSPACE LTD
1270 Aberdeen Street
Hawksbury, ON
K6A 1K7
Tél. : 1 613 632-9577

No item	Description	Qté	Qté livrée	Qté B/O
D2445P	Aft Door Assembly B139280 PO item: 30535/1 Lot: 2015-12-01	1		
D2445P	Aft Door Assembly B139281 PO item: 30535/2 Lot: 2016-01-07	1		

CANADIAN CURRENCY

SP16-02-17

Transport : _____
Nb colis : _____
Marchandise reçue : _____

Réf. : _____